

No.	Query	Answer
1	Group A: <u>A-1 Offshore Property (Marine Hull policy)</u>	
	Latest risk inspection report /Survey report on SPBM including photographs	TPI Report Attachment - 1
	Last 05 years claim history including Cause of loss, amount , location etc	Attachment - 2
	Exact structure of the SPBM	GA drawing Attachment - 3
	Who is responsible for maintenance and maintenance plan	Mechanical Engineer (SPBM)
	Value of the Buoy	US\$. 12,000,000
	Position of PLEM	Attachment - 4
	Survey report	TPI Report Attachment - 1
	Follow-up survey report	Not Applicable
	Survey recommendations	Refer Attachment - 1
	Thickness of all chains and other related details	Attachment - 5
	BV full report	Refer Attachment - 1
	Certificate of SPBM	Not class certified
	Dry dock report	Refer Attachment - 1
	Catalogues	Only for the use of CPC
	Any other relevant technical reports (if available)	Not Applicable
2	Group C: - <u>C-I Lanka 01 Boat (Marine Hull policy)</u>	
	Last 05 years claim history including Cause of loss, amount.	Nil
	Construction of the hull Ex Fibre etc.	Fibre
3	Group E : <u>E-1 Bunker Fuel at JCT oil Bank Bluemendhal</u>	
	Last 05 years claim history including Cause of loss, amount, Location etc	No claim / losses have been recorded during last five years.
	Maximum limit of storage at JCT oil bank at any point of time in LKR	USD 4,446,756.00
	Maximum number of days of storage at JCT oil bank.	Maximum seven (7) days
4	All other Groups (A-2, B & D) :-	
	Last 03 years claims history including Cause of loss, amount, Location etc.	Attachment -6

Table 02 - Clarifications & Answers (pre-bid meeting)

No.	Query	Answer
1	Should summery sheet values in Section 4 “Insurance Cover Bid Forms” for Groups A-D include or exclude VAT?	Indicate excluding VAT
2	Clarify the “Total Rate for Item No. E-1” on the Summery Sheet for Group-E	Indicate only the “Basic Rate”.